CITY OF PUNTA GORDA FIRE DEPARTMENT Fire Safety Inspection Report				INSPECTION TYPE	
				In-Service	
					PROPERTY USE
Business Name: Magdalena Gardens C		_			Assembly Education Healthcare
Business Address: 240 West End Dr. Unit: All Bldgs.				Storage Multi-Fam Motel/Hotel	
Business Phone: 941-575-6764					Business Mercantile Industrial
Contact Person #1: Sherry Danko	Phor	ne:	941-5	575-6764	Sq Ft: # Stories: 2
Contact Person #2:	Phon	ne:			Molnar, Jennifer - 305
RE-INSPECTION WILL OCCUR IN 30 days			C	1 Year	Inspector
# of violations 0					
A. GENERAL LIFE SAFETY	Υ	Ν	NA	C. EXTINGUI	ISHERS Y N NA
Are exits/exit aisles/stairs unobstructed?	\odot	\bigcirc	\bigcirc	 Are extingular 	uishers mounted at waist ht. at egress exit?
2. Are rated doors in a closed position?	•	0	0	2. Date of las	st service 2020/4
3. Do exit signs work on AC/DC power?	\bigcirc	0	O		tinguishers the correct type and size?
4. Does door opening hardware operate correctly?	•	0	0	 4. Is a portable the cooking 	ole fire (K) extinguisher located near g area?
5. Are the Knox Box keys present, marked & operational?	\odot	\bigcirc	\bigcirc	D. ELECTRIC	CAL EQUIPMENT
6. Are flammable and/or combustible liquids properly marked and stored in a vented flammable liquids cabinet?	\odot	\bigcirc	\bigcirc	1. Are electri	ical junction boxes enclosed?
7. Are fire lanes properly marked and unobstructed?	\bigcirc	\bigcirc	•	2. Do the em	nergency lights work?
Are proper address & unit numbers used/visibly posted?	•	\bigcirc	\bigcirc	3. Is all wiring	g properly enclosed and protected?
o. Are proper address a difficultibers disedivisibly posted:				4. Are surge cords?	protectors being used rather than extension
				Are electri	ical panels maintained to code, labeled
B. SPRINKLER/FIRE ALARM SYSTEMS				and acces	
Date of last sprinkler inspection			•		& BOOTH EXTINGUISHING SYSTEMS .
2. Are all valves open & accessible & identified?			••		uishing equipment maintained and provided rrent inspection tag?
3. Are the F.D.C.'s accessible and identified with signs?					stem, nozzles & filters clean & free of grease
4. Is there 18" clearance around sprinkler heads?	0	0	•	or paint b	NESS AND OTHER
5. Are standpipe connections and hose racks maintained and accessible?	\circ	\bigcirc	•		es are present and in good condition.
Are fire hydrants accessible & visible?	•	\bigcirc	\bigcirc	2. There is n	no storage in protected stairwells or under
7. Date of last fire alarm inspection	\bigcirc	\bigcirc	•		e no other hazards or deficiencies that will
Is the alarm system in operation and showing all				endanger operations	occupants or compromise fire department
systems clear? (No alarm or trouble lights)	\bigcirc	\bigcirc	\odot	operations	5.
The condition(s) indicated above may cause a fire, cont	ribute	to the	spre	ead of fire, or c	ause undue injury. The Fire Inspector will return to re-inspe
the property within APPROXIMATELY 30 DAYS to deter	mine c	ompl	iance	e. All questions	s should be referred to Fire Prevention at (941) 575-5529.
No visible fire violations at this time, annual fire safety inspect	passed	2020			
Inspect Date 8-6-2020 Compliance Date 2020-8	-b				<i>.</i> €
Occupant				Signat	ture NOT AVAILABLE
Telephone Email s.danko@starhospit	alityma	nager	ment.	com	